

**SUBJECT:** POWER PLANT, REDUCTION OF PROPELLER DIAMETER

**AIRCRAFT AFFECTED:** BEECHCRAFT Model A23-24 Musketeer, serials MA-1 through MA-208, MA-210 through MA-226, MA-228 through MA-240, MA-243, MA-244, MA-246 through MA-249, MA-252, MA-254 through MA-264, MA-266 through MA-268, MA-270 through MA-293, when such aircraft have installed McCauley Propeller 1B235/BFA7862.

**REASON FOR CHANGE:** To comply with McCauley Bulletin No. 67.

**ACCOMPLISHMENT:** As soon as is possible after the receipt of these service instructions.

**DESCRIPTION:** For BEECHCRAFT Musketeers, model and serials noted above, it is recommended that McCauley Bulletin No. 67 be complied with when such aircraft have installed McCauley propeller 1B235/BFA7862.

After complying with these service instructions, make an appropriate entry in the aircraft log book and return the attached compliance card to Beech Aircraft Corporation.

Beech Aircraft Corporation issues service information for the benefit of owners and fixed base operators in the form of three classes of Service Instructions. CLASS I (Red Border) are changes, inspections, and modifications that could affect safety. The factory considers compliance mandatory. CLASS II (Green Border) covers changes, modifications, improvements or inspections the factory feels will benefit the owner and although highly recommended, they are not considered mandatory compliance, unless specified at the time of issuance. Class I and II are mailed to:

- (a) BEECHCRAFT Aero or Aviation Centers and International Distributors and Dealers
- (b) Owners of record on the FAA Registration list and the

BEECHCRAFT International Owner Notification Service List:  
(c) Those having a publications subscription

CLASS III (No Border) covers changes which are optional, maintenance aids, product improvement kits and miscellaneous service information. Compliance is at the owner or operator's prerogative. Copies of Class III are distributed per a and c above. Information on Owner Notification Service or Subscriptions can be obtained through any BEECHCRAFT Aero or Aviation Center, International Distributor and Dealer, or the Factory. As Service Instructions are issued, temporary notation in the index should be made until the index is revised. Warranty will be allowed only when specifically defined in the Service Instructions and in accordance with Beech Warranty Policy.