

Beechcraft SERVICE LETTER

Published by the Customer Service Division

No. 65-19

Issued: July, 1965

INSPECTION OF WING TIP LIGHTS FOR PROPER COLOR

MODELS AFFECTED: All Beech Aircraft Co. Aircraft.

In relation to forward position lights, Civil Air Regulations state that:

" . . . with the airplane in normal flying position, the red light is displayed on the left side and the green light is displayed on the right side."

Any airplane not possessing such a light arrangement should be corrected as soon as possible. Refer to the respective BEECHCRAFT Parts Catalog for replacement parts.

THE OPERATION, CARE AND MAINTENANCE OF AN AIRPLANE IS THE OWNERS RESPONSIBILITY. AS CONDITIONS WARRANT, BEECH AIRCRAFT CORPORATION ISSUES SERVICE BULLETINS AND SERVICE LETTERS RECOMMENDING MODIFICATIONS AND OPERATIONAL PROCEDURES TO ENABLE THE OWNER TO GET THE MAXIMUM UTILITY AND SAFETY FROM HIS AIRPLANE.

THESE BULLETINS AND LETTERS ARE AVAILABLE TO BEECHCRAFT OWNERS THROUGH THEIR BEECHCRAFT DISTRIBUTOR OR DEALER. WHEN SERVICE BULLETINS AND LETTERS ARE ISSUED, A TEMPORARY RECORDING OF THE PUBLICATION SHOULD BE MADE ON THE APPROPRIATE INDEX.