

Beechcraft SERVICE LETTER

Published by the Customer Service Division

No. 66-5

KIT 23-9001

AFT COWL REINFORCEMENT

AIRCRAFT AFFECTED: BEECHCRAFT Musketeer A23A (M-901 through M-948).

Service experience reveals that addition of two reinforcement clips to the top aft cowling are desirable for stiffening the backbone and improving the reliability of the cowling. The clips may be installed as shown in the illustration (See reverse side).

Kit 23-9001 contains a packing sheet on which the parts for this retrofit are listed. It is suggested that this packing sheet be retained on file until such time as the listing of parts is included in the Parts Catalog.

266

THE OPERATION, CARE AND MAINTENANCE OF AN AIRPLANE IS THE OWNERS RESPONSIBILITY. AS CONDITIONS WARRANT, BEECH AIRCRAFT CORPORATION ISSUES SERVICE BULLETINS AND SERVICE LETTERS RECOMMENDING MODIFICATIONS AND OPERATIONAL PROCEDURES TO ENABLE THE OWNER TO GET THE MAXIMUM UTILITY AND SAFETY FROM HIS AIRPLANE.

THESE BULLETINS AND LETTERS ARE AVAILABLE TO BEECHCRAFT OWNERS THROUGH THEIR BEECHCRAFT DISTRIBUTOR OR DEALER. WHEN SERVICE BULLETINS AND LETTERS ARE ISSUED, A TEMPORARY RECORDING OF THE PUBLICATION SHOULD BE MADE ON THE APPROPRIATE INDEX.

Beech Aircraft Corporation - Wichita, Kansas 67201 USA - Founded in 1932 by Walter H. Beech

