

SERVICE BULLETIN

**Beechcraft
Hawker**

TITLE: GENERAL - HAWKER BEECHCRAFT PUBLICATIONS - WHAT IS AVAILABLE AND HOW TO OBTAIN IT

SYNOPSIS OF CHANGE

This service bulletin has been revised to announce a Corporation name change for Hawker Beechcraft Corporation (formerly known as Raytheon Aircraft Company). Relevant changes are marked with change bars in the outside margins. This Service Bulletin contains limited information about publications available and how to obtain them.

1. Planning Information

A. Effectivity

All Hawker Beechcraft Corporation non-military airplane models in service.

If you are no longer in possession of the airplane, please forward this information to the present owner.

B. Reason

This Service Bulletin has been revised to announce the Hawker Beechcraft Technical Publications Website as the chosen media to provide information on what technical publications are available, how to obtain them, and how to submit a Publication Change Request for any of the publications listed on the Website.

C. Description

NOTE

In the URL link listed below, areas that appear to be spaces are actually underscores.

Refer to the Hawker Beechcraft Technical Publications Website at <http://pubs.hawkerbeechcraft.com>. To submit a Publication Change Request, go to http://www.hawkerbeechcraft.com/service_support/pubs/docs/nontechnical/pcr_form_electronic.pdf.

The export of these commodities, technology or software are subject to the U.S. Export Administration Regulations. Diversion contrary to U.S. law is prohibited. For guidance on export control requirements, contact the Commerce Department's Bureau of Export Administration at <http://www.bis.doc.gov>.


Hawker Beechcraft Corporation (HBC) issues Service Information for the benefit of owners and fixed base operators in the form of two classes of Service Bulletins. The first class, Mandatory Service Bulletins (red border) includes changes, inspection and modifications that could affect safety or crashworthiness. HBC also issues Service Bulletins with no red border which are designated as either recommended or optional in the compliance section within the bulletin. In the case of recommended Service Bulletins, HBC feels the changes, modifications, improvements or inspections will benefit the owner/operator and although highly recommended, Recommended Service Bulletins are not considered mandatory at the time of issuance. In the case of Optional Service Bulletins, compliance with the changes, modifications, improvements or inspections is at the owner/operator's discretion.

Both classes are available on the web at <http://pubs.hawkerbeechcraft.com> and mailed to:

- Owners of record on the FAA Aircraft Registration Branch List and the HBC Safety of Flight Information (SOFI) List.
- Those having a publications subscription.

Information on Safety of Flight Information (SOFI) or subscription can be obtained through the Hawker Beechcraft Corporation Technical Manual Distribution Center (TMDC). As Mandatory Service Bulletins and Service Bulletins are issued, the Service Bulletin Master Index will be updated and available online at <http://pubs.hawkerbeechcraft.com>. Warranty will be allowed only when specifically defined in the Service Bulletin and in accordance with HBC Warranty Policy.

Unless otherwise designated, HBC Mandatory Service Bulletins, Service Bulletins and HBC Kits are approved for installation on HBC airplanes in original or HBC modified configurations only. HBC Mandatory Service Bulletins, Service Bulletins and Kits may not be compatible with airplanes modified by STC installations or modifications other than HBC approved kits.



SERVICE BULLETIN

NOTE

If unable to access the Hawker Beechcraft Technical Publications Website, contact the Technical Manual Distribution Center at telephone number 800.796.2665 or 316.676.8238, FAX number 316.671.2540 or mail to Technical Publications, Hawker Beechcraft Corporation, Attention: TMDC, for information or assistance in placing an order.

D. Compliance

Information only.

This Service Bulletin supersedes and cancels all revisions of Beechcraft Service Instructions No. 0250-010 and all prior revisions of Beechcraft and Raytheon Aircraft Service Bulletin No. 2001.

E. Approval

This Service Bulletin contains no engineering data requiring FAA approval.

F. Manpower

None.

G. Weight and Balance

None.

H. Electrical Load Data

Not applicable.

I. Software Accomplishment Summary

Not applicable.

J. References

Hawker Beechcraft Technical Publications Website: <http://pubs.hawkerbeechcraft.com>.

K. Publications Affected

None.

L. Interchangeability of Parts

Not applicable.

M. Warranty Credit

Not applicable.

SERVICE BULLETIN

2. Material Information

A. Materials - Price and Availability

Refer to the Hawker Beechcraft Technical Publications Website at <http://pubs.hawkerbeechcraft.com> for a complete list of all available Technical Publications with current revision status, price and availability.

B. Industry Support

Not applicable.

C. Airplanes

The following types of publications are available with applicable revisions for most models and are periodically revised by Hawker Beechcraft Corporation. A variety of media are available, including paper and CD-ROM.

- Airplane Flight Manuals
- Pilot/Crew Manuals/Checklists
- Parts and Wiring Catalogs
- Printed Circuit Board Manuals
- Wiring Diagram Manuals
- Shop/Overhaul Manuals
- Maintenance Manuals
- Component Maintenance Manuals
- Maintenance Requirements Manuals
- Maintenance Schedules and Programs
- Ground Handling Checklists
- Fault Isolation Manuals
- Weight and Balance Manuals
- Tool and Equipment Manuals
- Non-Destructive Testing Manuals
- Power Plant Build Manuals
- Inspection Forms
- Structural Inspection and Repair Manuals
- Corrosion Control Manuals

SERVICE BULLETIN

- Manual Supplements
- Safety/Service Information (Service Bulletins, Safety and Model Communiques) **available online at <http://pubs.hawkerbeechcraft.com>.**
- Passenger Information Cards
- Crash, Fire and Rescue Cards or Safety Information Cards (Also available as a downloadable file from the Hawker Beechcraft Technical Publications Website listed in Paragraph 1.J)

D. Spares

Not applicable.

E. Reidentified Parts

None.

F. Tooling - Price and Availability

Not applicable.

3. Accomplishment Instructions

The following information is provided as a general guide for requesting Hawker Beechcraft Corporation technical publications.

NOTE

Hawker Beechcraft Corporation does not supply FAA Airworthiness Directives. They may be ordered as follows: Superintendent of Documents, Government Printing Office, P.O. Box 371954, Pittsburgh, PA 15250-7954; Phone No. 202.512.1806; Fax 202.512.2250; World Wide Web at <http://av-info.faa.gov>.

A. Revision Service

NO CHARGE SERVICES

Safety of Flight Information (SOFI) List

Any Service Bulletin, Safety Communique, or revisions/reissues/supplements to Flight/Pilot's related manuals, including Pilot's Checklists, will automatically be mailed to the owners/operators of Hawker Beechcraft Corporation airplanes included on the SOFI List as the item is published. The SOFI List is produced based on the serial effectivity of the Service Bulletin/Communique. For inclusion on the SOFI List, please complete the form posted on the Hawker Beechcraft Technical Publications Website (see paragraph 1.J).

NOTE

Hawker /125 Series Crew Manuals are not covered by SOFI mailings.

NOTE

FAA registered owners do not need to sign-up for inclusion on the SOFI List. (See "FAA Registered Airplanes" below.)

SERVICE BULLETIN

NOTE

Service Bulletins and Communiques are also posted **for 90 days** on the Hawker Beechcraft website at <http://pubs.hawkerbeechcraft.com>. **A complete library of bulletins and communiques are available online with a subscription.**

FAA Registered Airplanes (United States Customers only)

The FAA List of Registered Owners mailing address list is used to send any service bulletins, safety communiques, pilot's operating handbook and FAA approved airplane flight manual revisions, reissues and supplements.

Changes cannot be made to an FAA mailing address by Hawker Beechcraft Corporation. If the airplane is registered to the owner and not the operator, the operator can purchase a subscription, or be added to the SOFI List.

SUBSCRIPTION SERVICES

An online subscription to Beechcraft and Hawker service bulletins and communiques is available by contacting TMDC at 800.796.2665 or 316.676.8238 or order online at <http://pubs.hawkerbeechcraft.com> (P/N OSI-B or OSI-H).

B. Publications Change Requests

NOTE

In the URL link listed below, areas that appear to be spaces are actually underscores.

Customers may submit Publications Change Requests for any of the Technical Publications listed on the Website. Customers are urged to enter as much information as possible, including contact numbers. Upon completion of the form (http://www.hawkerbeechcraft.com/service_support/pubs/docs/nontechnical/pcr_form_electronic.pdf), select the e-mail button and the Request will be sent directly to the Hawker Beechcraft Technical Support Department for review and Engineering concurrence, and then to the Technical Publications Department for priority placement and action.

4. Record of Compliance

Not applicable.