

No. 0105-241

19, 23

Kit No. 75528

SUBJECT: POWER PLANT, INSTALLATION OF OIL FILTER ON LYCOMING ENGINE.

AIRCRAFT AFFECTED: BEECHCRAFT Musketeers, Model 23, serials M-1 through M-554; Model B23, serials M-1095 and after; Models 19 and 19A, serials MB-1 and after.

On BEECHCRAFT Musketeers, models and serials noted above, a new oil filter assembly is available for installation at the owner's discretion. After installation of this filter assembly, it will be necessary only to order a replacement filter element, P/N 6435683, each time the filter needs changing. This will normally be every 50 hours, unless the engine has been operated in dusty conditions, which would require changing the element sooner.

The parts required for this rework are contained in Kit No. 75528. The Kit, when ordered, will include complete instructions for installation. It is suggested that the parts list included with these installation instructions be filed for future reference until the listing of parts has been incorporated into the parts catalog.

968

Beech Aircraft Corporation issues service information for the benefit of owners and fixed base operators in the form of three classes of Service Instructions. CLASS I (Red Border) are changes, inspections, and modifications that could affect safety. The factory considers compliance mandatory. CLASS II (Green Border) covers changes, modifications, improvements or inspections the factory feels will benefit the owner and although highly recommended, they are not considered mandatory compliance, unless specified at the time of issuance. Class I and II are mailed to:

- (a) BEECHCRAFT Aero or Aviation Centers and International Distributors and Dealers.
- (b) Owners of record on the FAA Registration list and the

BEECHCRAFT International Owner Notification Service List.
(c) Those having a publications subscription.

CLASS III (No Border) covers changes which are optional, maintenance aids, product improvement kits and miscellaneous service information. Compliance is at the owner or operator's prerogative. Copies of Class III are distributed per a and c above. Information on Owner Notification Service or Subscriptions can be obtained through any BEECHCRAFT Aero or Aviation Center, International Distributor and Dealer, or the Factory. As Service Instructions are issued, temporary notation in the index should be made until the index is revised. Warranty will be allowed only when specifically defined in the Service Instructions and in accordance with Beech Warranty Policy.