

23

No. 0929
ATA Code 11-30

SUBJECT: PLACARDS - INSTALLATION OF A FUEL RETURN DECAL

EFFECTIVITY: BEEHCRAFT A23 and A23A, serials M-555 through M-1094.

REASON: To provide a decal that details fuel management procedures for airplanes powered by Continental IO-346-A engines.

COMPLIANCE: Beech Aircraft Corporation considers this to be mandatory and it should be accomplished at the next scheduled inspection.

DESCRIPTION: A fuel return decal is installed on the instrument subpanel below the instrument cluster.

APPROVAL: FAA Approved - DOA CE-2.

MANPOWER: The following information is for planning purposes only:

Estimated man-hours: 0.5 hour.
Suggested number of men: 1 man.

MATERIAL: The 169-920034-3 decal required may be obtained through your BEEHCRAFT Parts and Service Outlet.

The value of the decal required for the incorporation of these Service Instructions on one airplane is to be advised. Price, when issued, will be subject to change without notice.

WARRANTY: Warranty credit for the 169-920034-3 decal and for labor to the extent noted under MAN-POWER will be allowed on claims submitted prior to November 1, 1978.

All warranty reimbursements are handled through franchised BEEHCRAFT outlets. Owners and operators may arrange with these outlets to perform the work and submit the standard Beech Aircraft Corporation warranty claim form to the Commercial Service Department, Beech Aircraft Corporation, Wichita, Kansas, 67201.

SPECIAL TOOLS: None.

WEIGHT AND BALANCE: None.

REFERENCES: None.

No BECP
1177 I

1 of 2

CLASS I

Beech Aircraft Corporation issues service information for the benefit of owners and fixed base operators in the form of three classes of Service Instructions. CLASS I (Red Border) are changes, inspections, and modifications that could affect safety. The factory considers compliance mandatory. CLASS II (Green Border) covers changes, modifications, improvements or inspections the factory feels will benefit the owner and although highly recommended, they are not considered mandatory compliance, unless specified at the time of issuance. Class I and II are mailed to:

- (a) BEEHCRAFT Aero or Aviation Centers and International Distributors and Dealers.
- (b) Owners of record on the FAA Registration list and the

BEEHCRAFT International Owner Notification Service List.
(c) Those having a publications subscription.

CLASS III (No Border) covers changes which are optional, maintenance aids, product improvement kits and miscellaneous service information. Compliance is at the owner or operator's prerogative. Copies of Class III are distributed per a and c above. Information on Owner Notification Service or Subscriptions can be obtained through any BEEHCRAFT Aero or Aviation Center, International Distributor and Dealer, or the Factory. As Service Instructions are issued, temporary notation in the index should be made until the index is revised. Warranty will be allowed only when specifically defined in the Service Instructions and in accordance with Beech Warranty Policy.

Service Instructions No. 0929

PUBLICATIONS AFFECTED: It is recommended that a note to "See Service Instructions No. 0929" be made in all 19, 23, and 24 series Parts Catalog copies, P/N 169-590012I or subsequent, Figure 16.

ACCOMPLISHMENT INSTRUCTIONS: These Service Instructions may be accomplished as follows:

1. Clean the instrument subpanel below the instrument cluster with naphtha or equivalent to remove dirt and film.
 2. Install the 169-920034-3 pressure sensitive decal below the instrument cluster.
-

RECORD COMPLIANCE: Upon completion of these Service Instructions make an appropriate maintenance record entry.